Ref #	Hits	Search Query	DBs	Default Operat or.	Plural s	Time Stamp
L1	28	(shock near4 damp\$6) near6 cycle	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/04/02 15:06
L2	1	1 and ((torque torsion tension) near4 (detect\$4 sens\$4 measur\$4 indicat\$4 monitor\$4 calculat\$4 cell gage gauge transducer))	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/04/02 15:01
L3	79020	((torque torsion tension) near4 (detect\$4 sens\$4 measur\$4 indicat\$4 monitor\$4 calculat\$4 cell gage gauge transducer))	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/04/02 15:04
L4	74	3 and ((shock damp\$6) near6 cycle)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/04/02 15:02
L5	. 1	3 and ((shock near6 damp\$6) near6 cycle)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/04/02 15:02
L6	195	(shock near4 (absorb\$5 damp\$6)) near6 cycle	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/04/02 15:03
L7	2	6 and ((torque torsion tension) near4 (detect\$4 sens\$4 measur\$4 indicat\$4 monitor\$4 calculat\$4 cell gage gauge transducer))	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/04/02 15:04
L8	6	1 and (torque torsion tension)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/04/02 15:08
L9	1558	crank near3 axle	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/04/02 15:08
L10	54	((crank near3 axle) near6 (detect\$4 sens\$4 indicat\$4 transducer gage gauge cell measur\$6 calculat\$4))	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/04/02 15:09
LII	15	10 and cycle	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/04/02 15:14

L12	16	10 and (bike cycle)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/04/02 15:18
L13	3	12 and ((mov\$5 motion displac\$6) near4 cable)	US-PGPU B; USPAT; EPO; JPO	OR	OFF	2005/04/02 15:19